

UUID
41cabf0b-213c-452c-b9f0-9a434dc5c234

Date
2023-05-09 09:17:53

VIN
Make
VW
Model



UUID
41cabf0b-213c-452c-b9f0-9a434dc5c234

Date
2023-05-09 09:17:53

VIN **Make** **Model**
 VW

Part size[mm]	Dent						Scratch						CoatingDamage					
	<10	<20	<30	<50	>50	Σ	<10	<20	<30	<50	>50	Σ	<10	<20	<30	<50	>50	Σ
Trunk lid	0	0	2	0	0	2	0	0	1	0	0	1	0	0	0	0	0	0
unknown partID 6750105	0	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0
unknown partID 16764057	0	0	0	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0
Roof	0	0	0	1	0	1	0	4	8	2	0	14	1	0	0	0	0	1
Hood	1	1	0	0	0	2	0	14	7	6	2	29	0	0	0	0	0	0
Bumper rear	0	1	0	0	0	1	0	1	0	0	2	3	0	1	0	0	0	1
Side panel right	0	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0
Bumper front	1	0	0	0	0	1	0	4	1	0	0	5	0	0	0	0	0	0
Side panel left	0	0	0	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0
Door front left	1	0	0	0	0	1	0	5	1	4	4	14	1	0	0	0	0	1
Door rear left	0	0	0	0	0	0	0	6	3	4	2	15	1	0	0	0	0	1
Door rear right	0	0	0	0	0	0	0	8	6	4	1	19	0	0	0	0	0	0
Door front right	0	0	0	0	0	0	0	8	5	2	1	16	4	0	0	0	0	4
Fender front right	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	0

UUID 41cabf0b-213c-452c-b9f0-9a434dc5c234	Date 2023-05-09 09:17:53	VIN	Make VW	Model
---	------------------------------------	------------	-------------------	--------------

part	reason	action	cost
Bumper front	small dents, scratch	Smart Repair	195.0
Door front left	coating damage, scratch	Smart Repair	250.0
Door front right	large number of scratches, many small scratches	Repair Part	419.2
Door back left	coating damage, scratch	Smart Repair	400.0
Door back right	scratch	Smart Repair	150.0
Side body right	scratch	Smart Repair	50.0
Roof	coating damage	Smart Repair	50.0
Roof rail left	scratch	Smart Repair	50.0
Trunk/Trunklid	dents	Repair Part	419.2
sum			1983.4
fe160fcc03a29a4c34b1a68bb2aa84ac8d7f28fa1365c6dcbf736c0058d1b9bf			